

Dátový list pre produkt: HSEDA40WP

Optická zásuvka povrchová, 80×28×80mm prázdna pre 4 adaptéry

RAL9010 biela, možnosť inštalácie na DIN lištu



SCHRACK-Info

FTTH empty outlets serve as a universal interface for fiber optic installations.

They offer a high degree of flexibility when it comes to equipping and adapting the network infrastructure.

Empty outlets are an ideal solution for organizing the fiber-optic connection efficiently and ensuring a clean, well-structured installation—especially when planning for future expansions or upgrades of the network structure.

Features

- Fiber Optic In-House-Cabling
- Offers connection options for up to 4 end devices
- The box is suitable for pre-assembled cables or for pigtails

- Flexible cable entry options
- Lid locks into place
- 2 screws, 2 dowels, and 2 shrink splice protectors included

Optional Accessories

Couplers:

- HSELSK09MR
- HSELSK09GR

Pigtails:

- HLP09M041P
- HLP09D041P

Safety information:

Avoid direct contact with light sources:

- Fiber optic cables—especially those with active light sources such as lasers (e.g., in optical communication systems)—can emit hazardous radiation that may damage the eyes.
- Never look directly into the light of a fiber optic cable, even if the light source is invisible to the naked eye.

Wear protective eyewear:

- When working with fiber optic cables, especially during tests or when using lasers, always wear safety glasses to protect your eyes from harmful radiation.

Handle cables correctly:

- Plug in and unplug cables only by holding the connector, and never pull directly on the cable.

Do not bend or crush:

- Fiber optic cables are sensitive to mechanical stress.

Protect from damage:

- Install cables in dedicated conduits or use protective materials to prevent physical damage.

Keep connectors clean:

- Fiber optic connectors must be free of dust and dirt.
- Even small particles on the connectors can significantly reduce signal quality.

Observe temperature limits:

- Do not expose cables to extremely high or low temperatures.
- Follow the manufacturer's specifications for the cable's maximum operating temperature.


Inspect regularly:

- Frequently check cables for visible damage such as cracks, bends, or signs of wear.
- Damaged cables must be replaced immediately.

Technické informácie

Šírka (mm)	80,00
Výška (mm)	28,00
Hmotnosť (kg)	0,05
Farba	RAL 9010 (čistá biela)
Min. teplota okolia (°C)	-40
Max. teplota okolia (°C)	75

Rozmerový obrázok: Optická zásuvka povrchová, 80×28×80mm prázdna pre 4 adaptéry



Tabuľka objednávacích čísel

POPIS	OBJ. ČÍSLO
Optická zásuvka povrchová, 80×28×80mm prázdna pre 4 adaptéry RAL9010 biela, možnosť inštalácie na DIN lištu	HSELDA40WP
Voliteľné príslušenstvo	
Optická spojka LC/APC-Duplex, plastová, OS2, keramická bez príruby, zelená, protiprachový kryt, CLASSIC	HSELSK09MR
Optická spojka SC/APC-Simplex, plastová, OS2, keramická bez príruby, zelená, protiprachový kryt, CLASSIC	HSELSK09GR
FTTH FO Pigtail LC/APC 8°, 9/125µm OS2 G657.A2, 1.0m, 4 ks Easy Strip, farebný podľa IEC 60304, CLASSIC	HLP09M041P
FTTH FO Pigtail SC/APC 8°, 9/125µm OS2 G657.A2, 1.0m, 4 ks Easy Strip, farebný podľa IEC 60304, CLASSIC	HLP09D041P
Čistiace pero na optické konektory LC a MU Vhodné pre konektory UPC a APC. Viac ako 1 000 čistiacich cyklov.	HSELSZT001
Čistiace pero na optické konektory SC, ST, FC a E2000 Vhodné pre konektory UPC a APC. Viac ako 1 000 čistiacich cyklov.	HSELSZT002
Opt. hladinomer s integrovaným laserovým zdrojom svetla(VFL) Test medeného kábla RJ45. POZOR: Toto je laserový výrobok triedy 2. Nepozerajte sa do lúča. Vždy majte kryt na porte VFL, keď sa nepoužíva. Pri práci s optickými systémami sa odporúča používať ochranné okuliare proti laseru.	HSELSZT003